

State of Utah

Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:							
Company	Dennis Oakley Environmental Engineer						
OGM	Steve Demczak Environmental Scientist III						

Inspection Report

Permit Number:	C0150017		
Inspection Type:	PARTIAL		
Inspection Date:	Tuesday, January 15, 2008		
Start Date/Time:	1/15/2008 12:00:00 PM		
End Date/Time:	1/15/2008 2:00:00 PM		
Last Inspection:	Monday, December 10, 2007		

Inspector: Steve Demczak, Environmental Scientist III

Weather: Cold, Teens, Snow Covered InspectionID Report Number: 1529

Accepted by: dhaddock

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DES BEE DOVE MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	154.86
Total Disturbed	36.22
Phase I	
Phase II	
Phase III	

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface Loadout County Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Water monitoring activities at this site have been discontinued with the reclamation of the last UPDES outfall (the sediment pond discharge point).

The 2006 Annual Report for the Des-Bee-Dove site was received at the DOGM on May 1, 2007. Review of the submitted information is pending.

Inspector's Signature:

Steve Demczak, Environmental Scientist III

Date

Thursday, January 17, 2008

Inspector ID Number: 39

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

1594 West North Temple, Suite 1210, PO Box 145801, Salt Lake City, UT 84114-5801 telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 15, 2008

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcemen
1.	Permits, Change, Transfer, Renewal, Sale	✓		\checkmark	
2.	Signs and Markers				
3.	Topsoil	✓		✓	
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓		V	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading	✓		V	
13.	Revegetation	✓		✓	
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	a Roads: Construction, Maintenance, Surfacing	✓		V	
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations	V		✓	
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Tuesday, January 15, 2008

Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

No new permitting action has been submitted since the last inspection.

3. Topsoil

All topsoil has been used in the reclamation of Des Bee Dove.

4.c Hydrologic Balance: Other Sediment Control Measures

No signs of sediment coming off site.

8. Noncoal Waste

No non-coal waste was noticed.

12. Backfilling And Grading

The site is backfilled and graded.

13. Revegetation

The site is seeded.

16.a Roads: Construction, Maintenance, Surfacing

No roads go through the site.

18. Support Facilities, Utility Installations

There are no support facilities or utility installations.